



*Technical Note*

**Release note for visionlinkserver**

---

Document No: TN-0075

This document is proprietary and confidential. No part of this document may be disclosed in any manner to a third party without the prior written consent of Vision Remote.

# 1 General

## 1.1 Purpose

This document contains SW release notes for the Visionlinkserver. These notes contains relevant information for end users that want to download and install the latest software from our homepage.

## 1.2 Common code base

This code for visionlinkserver is common for both VX-100 and VM-110. Under each release there will be a comment for which platform the release is valid.

# 2 Release history

## VisionLink Server 2.2.0

Date: 2024-03-12

Changes:

- Added support for more radio modules (419 MHz, 459 MHz and 1.2 GHz)

Compatibility notes:

- Units which has installed visionlinkserver-vm-2.1.2-qt6.run must upgrade to the latest Linux (VREL 24.02(r1) or later) before upgrading to this version of VisionLink Server.

---

## VisionLink Server 2.1.2

Date: 2024-03-12

Changes:

- Bug fixes: VisionLink app checksum too slow and Fallback fails to initialize
- Compiled for two different Linux versions to support QT5 for older versions and QT6 for new ones.

Compatibility notes:

- Valid for VM-110 only.
- visionlinkserver-vm-2.1.2-qt5.run for all BUs with serial number up to AB0109.
- visionlinkserver-vm-2.1.2-qt6.run for BUs with serial number AB0110 or higher.
  - BUs with serial number AB0110 or higher will only work with version 1.3.13 and 2.1.1 or newer.

---

## VisionLink Server 2.1.1

Date: 2023-11-13

Changes:

- Introduces VLAP sharing. Allows G-Link server to be started on a different IP than 192.168.32.1 (configurable in web interface).

Document No: TN-0075

- Fixes bug in G-Link where commands with matching timestamps are dropped.
- Compiled for two different Linux versions to support QT5 for older versions and QT6 for new ones.

Compatibility notes:

- Valid for VM-110 only.
- visionlinkserver-vm-2.1.1.run for all BUs with serial number up to AB0109.
- visionlinkserver-vm-2.1.1-qt6.run for BUs with serial number AB0110 or higher.
  - BUs with serial number AB0110 or higher will only work with version 1.3.13 and 2.1.1 or newer.

---

## VisionLink Server 2.1.0

Date: 2023-09-18

Changes:

- Complete rewrite of G-Link protocol and software. See TS-0012 rev. 3 for details.
- Improvements to G-Fallback
- Changes fieldbus data to be transferred and stored in complete blocks before forwarded on G-Link/G-Fallback and written to software tags
- Fixed bug in transport layer where empty acknowledge was not forwarded to service
- Simplified FSM in SystemEventService class
- Added (user overwritable) timestamps and colorization to BU log file
- Update FW to VM-110-BC-2-3

Compatibility notes:

- Valid for VM-110 only

---

## VisionLink Server 2.0.0

Date: 2023-02-28

Changes:

- Adds support for MultiArm. Internal release only.

Compatibility notes:

- Valid for VM-110 only. VX-100 must still use Version 1.x.x.

---

## VisionLink Server 1.3.13

Date: 2022-07-03

Changes:

- Add Linux sync command at end of vrsetup.sh
- No changes in VisionlinkServer – new version to signal update only.

Document No: TN-0075

Compatibility notes:

- Update for VM-110 and VX-100
- 

## VisionLink Server 1.3.12

Date: 2022-03-27

Changes:

- BC firmware update – VM-110-BC-1-12
- No changes in VisionlinkServer – new version to signal update only.

Compatibility notes:

- Update for VM-110 and VX-100